

Body & Frame, Inc

Damage Assessed By: [REDACTED]

Deductible: UNKNOWN

Owner: [REDACTED]
 Address: [REDACTED] CA 95670
 Telephone: [REDACTED] Work Phone: (916) [REDACTED] Home Phone: [REDACTED]

Mitchell Service: 913501

Description: 2004 Cadillac CTS
 Body Style: 4D Sed
 VIN: 1G6DM577240143272
 OEM/ALT: O

Drive Train: 3.6L Inj 6 Cyl 5A RWD

Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/Part Number	Dollar Amount	Labor Units
1	301559	BDY	REMOVE/INSTALL	L WSHIELD GARNISH MLDG	Existing		0.3 #
2				R&R Time Used in R&I Operation			
3	300822	BDY	REMOVE/INSTALL	L FRT DOOR WEATHERSTRIP	Existing		0.4
4				R&R Time Used in R&I Operation			
5	300842	REF	BLEND	L REAR DOOR OUTSIDE			C 0.8
6	300858	BDY	REMOVE/INSTALL	L REAR OTR BELT MOULDING			0.2
7	300860	BDY	REMOVE/INSTALL	L REAR DOOR ADHESIVE MOULDING	Existing		0.2
8				R&R Time Used in R&I Operation			
9	300868	BDY	REMOVE/INSTALL	L REAR DOOR TRIM PANEL			INC
10	300904	BDY	REMOVE/INSTALL	L REAR DOOR HANDLE			0.6 #
11	301750	BDY	REMOVE/INSTALL	L REAR LWR DOOR WEATHERSTRIP	Existing		0.2
12				R&R Time Used in R&I Operation			
13	900500	REF *	REFINISH/REPAIR	BLEND LT ROOF RAIL	Existing		1.5*
14	900500	BDY *	ADD'L LABOR OP	ROPE BACK GLASS	Existing		0.5*
15	300941	BDY	REMOVE/INSTALL	L ROOF ADHESIVE MOULDING	Existing		0.2
16				R&R Time Used in R&I Operation			
17	301000	REF	REFINISH	L SIDE BODY PANEL COMPLETE			C 2.8*
18	301037	BDY	REPAIR	L SIDE BODY PANEL ASSEMBLY	-S Existing		6.0*
19	301070	BDY	REMOVE/INSTALL	L REAR ROCKER MOULDING			0.5 #
20	301102	REF	BLEND	LUGGAGE LID			C 0.9
21	301114	BDY	REMOVE/REPLACE	LUGGAGE LID ADHESIVE NAMEPLATE	25765400 GM PART	20.63	0.2

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	11.7	75.00	0.00	0.00	877.50	Taxable Parts	20.63
Refinish	11.8	75.00	7.50	0.00	892.50	Sales Tax @ 7.750%	1.60
Non-Taxable Labor					1,770.00	Total Replacement Parts Amount	22.23
Labor Summary	23.5				1,770.00		

III. Additional Costs	Amount	IV. Adjustments	Amount
Taxable Costs	370.00	Customer Responsibility	0.00
Sales Tax @ 7.750%	28.68		
Non-Taxable Costs	12.50		
Total Additional Costs	411.18		

I. Total Labor:	1,770.00
II. Total Replacement Parts:	22.23
III. Total Additional Costs:	411.18
Gross Total:	2,203.41
IV. Total Adjustments:	0.00

5034

Invoice

9521 Greenback Lane #200
 Folsom CA 95630
 (916) 296-3368

Customer:

Bruce

Gold River CA 95670


()

Inv Date: 24-Jan-2008

Year	Color	Make	Model	Stocknbr
	Green	Cadillac	cts	



Panel	Description	Price
12	LT. 1/4 Panel	\$170.00
TOTAL		\$170.00



Sum:

Method:

Date:

Ref No:

Paid: \$170.00 Check 1/24/2008 7005

make 95% better

Thanks ! Tell your friends about Dent Shoppe.
 We appreciate your business.