

Date: 10/ 8/2008 11:23 AM  
 Estimate ID: 4301  
 Estimate Version: 0  
 Preliminary  
 Profile ID: CUSTOMIZED

Damage Assessed By: CAROLYN ROYAL

Deductible: UNKNOWN

Owner:  
 Address:  
 Telephone: Work Phone: Home Phone:

Mitchell Service: 918287

Description: 2006 Mercedes-Benz C230  
 Body Style: 4D Sed  
 VIN:  
 Color: WHITE  
 Options: LEATHER SEATS, AUTOMATIC TRANSMISSION

Vehicle Production Date: 2/06  
 Drive Train: 2.5L Inj 6 Cyl 7A RWD

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	800017	BDY	REMOVE/INSTALL	FRT BUMPER ASSY			1.0
2	800046	BDY	REMOVE/INSTALL	GRILLE ASSY			0.4 #
3	801734	BDY	REMOVE/INSTALL	R FRT COMBINATION LAMP			0.3 #
4	800101	REF	BLEND	HOOD OUTSIDE			C 1.0
5	800107	BDY	REMOVE/INSTALL	ORNAMENT			0.2
6	800108	BDY	REMOVE/INSTALL	HOOD GRILLE			0.3
7	807955	BDY	REPAIR	R FENDER PANEL	Existing		2.5*#
8	AUTO	REF	REFINISH	R FENDER OUTSIDE			C 2.0
9	800209	BDY	REMOVE/INSTALL	R LWR FENDER FRONT LINER	Existing		0.3
10				R&R Time Used in R&I Operation			
11	800211	BDY	REMOVE/INSTALL	R UPR FENDER FRONT LINER	Existing		0.2
12				R&R Time Used in R&I Operation			
13	800213	BDY	REMOVE/INSTALL	R FENDER REAR LINER	Existing		0.3
14				R&R Time Used in R&I Operation			
15	800237	BDY	REMOVE/INSTALL	R FENDER MOULDING			0.3
16	936012		ADD'L COST	HAZARDOUS WASTE DISPOSAL		5.00 *	
17	AUTO	REF	ADD'L OPR	CLEAR COAT			1.1
18	933003	REF	ADD'L OPR	TINT COLOR			0.5*
19	933005	BDY	ADD'L OPR	RESTORE CORROSION PROTECTION		15.00 *	0.3*
20	933017	REF	ADD'L OPR	FINISH SAND AND BUFF			1.0*
21	933018	REF	ADD'L OPR	MASK FOR OVERSPRAY		10.00 *	0.5*
22	AUTO		ADD'L COST	PAINT/MATERIALS		165.60 *	

\* - Judgment Item  
 # - Labor Note Applies  
 C - Included in Clear Coat Calc

ESTIMATE RECALL NUMBER: 10/08/2008 11:23:07 4301

Mitchell Data Version: OEM: JUL\_08\_A

UltraMate is a Trademark of Mitchell International  
 Copyright (C) 1994 - 2008 Mitchell International

UltraMate Version: 6.5.019

All Rights Reserved

## Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	6.1	82.00	15.00	0.00	515.20		
Refinish	6.1	82.00	10.00	0.00	510.20		
Non-Taxable Labor					1,025.40		
Labor Summary	12.2				1,025.40		
					Total Replacement Parts Amount		0.00
					Total Labor:		1,025.40
					Total Replacement Parts:		0.00
					Total Additional Costs:		182.61
					Gross Total:		1,208.01
					Total Adjustments:		0.00
					Net Total:		1,208.01

**This is a preliminary estimate.**  
**Additional changes to the estimate may be required for the actual repair.**

5619

## Invoice

9521 Greenback Lane #200  
 Folsom CA 95630  
 (916) 296-3368



Customer:

El Dorado Hills CA 95762

( ) Inv Date: 8-Oct-2008

Year	Color	Make	Model	Stocknbr
2006	White	Mercedes	C23	

Panel	Description	Price
4	RT. Front Fender	\$85.00
<b>TOTAL</b>		<b>\$85.00</b>

3	85.00	5	6	7	8
2					9
1					17
16	15	14	13	12	11



Sum:

Method:

Date:

<b>Paid:</b>	\$85.00	Visa	10/8/2008
--------------	---------	------	-----------

Thanks ! Tell your friends about Dent Shoppe.  
 We appreciate your business.